

SLAC Activities Update

University of Wisconsin

Shaun Alsum

LZ Madison Group Meeting

November 16



WISCONSIN
UNIVERSITY OF WISCONSIN-MADISON



- Compressor circulation tests through the getter on the R&D panel to test the compressor under load and at higher pressures.
- Started disassembly of R&D vessels.
- Started diagnosing problems with sensors
 - R&D vessel Level Sensor D25 was not plugged in on inner side of the feedthrough.
 - Weir reservoir level sensor beeps out all connections correctly, still trying to diagnose.
 - Three RTDs in the R&D vessel not working correctly
 - One had a short at the RTD itself, wire holding it to the stick bit through teflon tape supposed to be insulating it and shorted the two sides.
 - One seems to have a short ~3/20ths of the way up the wire based on measurements made at the PLC.
 - One shorts occasionally when shifted, but is fine much of the time which makes it hard to troubleshoot.

- Also struggling to untangle and rewind, re-label, and pull out cables for reorganization and re-insertion.

