


Problem with KB0090

Kimberly Palladino

March 2, 2016



Everything looks ok

- PMT looks fine on inspection







Ramp Up: Stops working

- See some PE ~-1000 V, better at -1200 to -1260
- Very little after pulsing
- Current draw from supply matches Ohms law for 92.4 M Ω base: ~13 μ A at -1250 V
- Abruptly at 1275-1285 (differs by 5 V in different ramp ups) current jumps to double, 26 μ A and stop seeing PE
- Must drop to <500V for current draw to return to normal



More Afterpulsing



PMT tested at Brown

