Progress Update on SolidWorks -> Geant4 Converter

Carl Vuosalo

University of Wisconsin-Madison

Obtained Full LZ Detector Design

- Oct. 2014 LZ design
- 400 MB in size
- Contains hundreds of components
- Converter takes two hours to process file
- Doesn't crash, but output not correct
- Most components seem incomplete
 - May be "lightweight" components

Full LZ Design

SolidWorks Design

Same Design in Geant4

- Converter output incomplete and incorrect, but not randomly distributed
- Lot more work to handle new SolidWorks features

One Assembly: Water Tank

SolidWorks Design

Same Design in Geant4

- Water tank appears (incorrectly) in Geant4 – why not in full design?
  - ➤ Maybe components are suppressed in full design
- Some mates are wrongly interpreted, so parts are misplaced