

SLAC Activities Update

University of Wisconsin

Shaun Alsum

LZ Madison Group Meeting

November 9



WISCONSIN
UNIVERSITY OF WISCONSIN-MADISON



- Compressor primed and circulation tested on its panel and heat exchanger.
- Compressor interlocks tested, and many fixed.
- More high voltage tests done at different pressures to try to help diagnose the issue.
- Weighed and tagged newly arrived Xe.
- Continued looking into gamma simulations (in down time so just working through revamping geometry still).
- Removed Xe from the detector.