

Twiki page: LZ QA

Yitong Liu
04/17/2018

- QA = Quality Assurance, make sure the LZ detector will work in the end
- Pick, check, assemble, accept, document
- Adding information/links to the Twiki page about QA on gas xenon(ship Xe gas storage packs from PSL to SLAC).